

3/6




FIG. 3



E: LOW PROFILE CONTACT ASSEMBLY  
INVENTOR: F. Morana, et al.  
S.N.: 10/824,799  
DOCKET: 18034 (AT #20958-02110)  
ATTORNEY: Bruce Atkins; PHONE: (314)621-5070  
REPLACEMENT SHEET

5/6




FIG. 5